

United States Steel Corporation Clainton Works 400 State Street Clainton, PA 15025 42-003-00032

NECTIVED

February 25, 2014 3AP20

Ms. Gail Eddings Allegheny County Health Department Department of Air Quality 301 Thirty-Ninth Street Pittsburgh, PA 15201

Subject: USS Reference Number: 14-0052

ACHD Reference Number: 16838

100 Carbonate Plant USS Clairton Works

Dear Gail Eddings,

The attached form confirms our verbal report of the subject incident and satisfies the requirements of paragraph IV.8 of the Title V operating permit #0052 as issued on March 27th 2012.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Thomas E. Schumacher

Plant Manager Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

- 1. USS Reference Number: 14-0052 ACHD Reference Number: 16838
- 2. Date & Time of Breakdown: Date: 02/24/14 Time: 1600 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: 100 Carbonate Plant
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: The 100 Carbonate Plant will be unavailable for service to repair the reboiler.

The 100 Carbonate Unit is a redundant piece of equipment. Gas processing for sulfur removal will be handled by the 600 Carbonate Unit. Sulfur Plant performance will not be affected. Sulfur emissions will not increase.

- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
 The 600 Carbonate Plant will carry the full acid gas flow to the plant. No environmental impact is expected.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A. No environmental impact is expected
 - C. Amount of each type emitted (or likely to be emitted). N/A.
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). The 600 Carbonate Plant will carry the full acid gas flow to the plant.
- 10. Facility back in operation Date: Time: Hours

Reviewed by (clero h. Javo Date 2-25-14

Senior Environmental Control Engineer Phone: 412-233-1015